

1 UK-TYPE EXAMINATION CERTIFICATE

2 Safety Device, Controlling Device or Regulating Device intended for use outside a potentially explosive atmosphere but required for or contributing to the safe functioning of Product and Protective Systems with respect to the risks of explosion

UKSI 2016:1107 (as amended) – Schedule 3A, Part 1

3 UK-Type Examination

BAS21UKEX0461

Certificate Number:

4 Product: MTL5532 Pulse Isolator

5 Manufacturer: Eaton Electric Limited

6 Address: Great Marlings, Butterfield, Luton, Bedfordshire, LU2 8DL

- 7 This product and any acceptable variation thereto is specified in the schedule to this certificate and the documents therein referred to.
- SGS Baseefa, Approved Body number 1180, in accordance with Regulation 43 of the Equipment and Protective Systems Intended for Use in Potentially Explosive Atmospheres Regulations 2016, UKSI 2016:1107 (as amended), certifies that this product has been found to comply with the Essential Health and Safety Requirements relating to the design and construction of products intended for use in potentially explosive atmospheres given in Schedule 1 of the Regulations.

The examination and test results are recorded in confidential Report No. 21(C)0386/13

9 Compliance with the Essential Health and Safety Requirements has been assured by compliance with:

EN IEC 60079-0:2018 EN 60079-11:2012

except in respect of those requirements listed at item 18 of the Schedule.

- 10 If the sign "X" is placed after the certificate number, it indicates that the product is subject to the Specific Conditions of Use specified in the schedule to this certificate.
- 11 This UK-TYPE EXAMINATION CERTIFICATE relates only to the design and construction of the specified product. Further requirements of the Regulations apply to the manufacturing process and supply of this product. These are not covered by this certificate.
- 12 The marking of the product shall include the following:

E II (1) GD [Ex ia Ga] IIC (-20°C \leq Ta \leq +60°C) [Ex ia Da] IIIC (-20°C \leq Ta \leq +60°C)

 $\langle E \rangle$ I (M1) [Ex ia Ma] I (-20°C Ta \leq +60°C)

SGS Baseefa Customer Reference No. 0703

Project File No. 21/0386

This document is issued by the Company subject to its General Conditions for Certification Services accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. It does not necessarily indicate that the equipment may be used in particular industries or circumstances. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, schedule included, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Baseefa Limited

Rockhead Business Park, Staden Lane,
Buxton, Derbyshire SK17 9RZ

Telephone +44 (0) 1298 766600 Fax +44 (0) 1298 766601
e-mail baseefa@sgs.com web site

www.sgs.co.uk/sgsbaseefa

Registered in England No. 4305578.
Registered address: Rossmore Business Park, Ellesmere Port, Cheshire,
CH65 3EN



RSS: Omi

R S SINCLAIR TECHNICAL MANAGER On behalf of SGS Baseefa Limited



Issued 11 January 2022 Page 2 of 5

Schedule 13

Certificate Number BAS21UKEX0461

15 **Description of Product**

14

The MTL5532 Pulse Isolator is designed to restrict the transfer of energy from unspecified non-hazardous area apparatus to a switch, proximity detector, current pulse transmitter or voltage pulse transmitter located in the hazardous area by limitation of voltage and current. Transformers, an opto-isolator and a relay provide galvanic isolation between the hazardous and nonhazardous area circuitry.

The MTL5532 Pulse Isolator is designed for connection of a switch, proximity detector, current pulse transmitter or voltage pulse transmitter situated in the hazardous area. The apparatus repeats the pulse signals from the apparatus in the hazardous area onto outputs in the non-hazardous area. An alarm circuit provides a relay contact output in the non-hazardous area to indicate a failure.

The equipment comprises isolating transformers, an opto-isolator, a relay, duplicated zener diodes chains and current limiting resistors to provide voltage and current limitation. The above, together with other electronic components are mounted on a printed circuit board (PCB) and housed in a moulded plastic enclosure. Polarised plugs and sockets are provided for hazardous and nonhazardous area connections. A jack socket is provided for the connection of a suitably certified data terminal for programming the apparatus.

Input / Output Parameters

Non-Hazardous Area Terminals 7 to 14

 $U_m = 253V \text{ r.m.s.}$

The circuit connected to non-hazardous area terminals 7, 8, 9, 10, 13 & 14 is designed to operate from a d.c. supply voltage of up to 35V.

Non-hazardous area terminals 11 & 12 are connected to relay contacts which can switch up to 250V r.m.s. or 5A r.m.s. or 100VA.

Hazardous Area Terminals 2 w.r.t. 1, Hazardous Area Terminals 6 w.r.t. 1 or Hazardous Area Terminals 6 w.r.t. 3

10.5V $I_o = 14mA$

 $P_0 = 37 \text{mW}$

Hazardous Area Terminals 3 w.r.t. 1

 $U_i = 30V$ $U_o = 1.1V$ $C_i = 0$ $I_o = 53mA$ $I_i = 100 \text{mA}$

Although the apparatus does not comply with the simple apparatus requirements of Clause 5.7 of EN 60079-11: 2012, when terminals 3 w.r.t. 1 are connected in an intrinsically safe circuit the internal stored energy, voltage and current of the interface will not add more than the values specified in Clause 5.7 of EN 60079-11: 2012 to the parameters of the circuit into which it is connected.

When an external intrinsically safe source is connected to these terminals it should have a source resistance of Ui / Ii and the capacitance and either the inductance or inductance to resistance ratio (L/R) of the hazardous area connections must not exceed the values detailed in the certificate of the intrinsically safe source. Hazardous area terminals 2, 4, 5 and 6 must not be used when the source is connected.



Hazardous Area Terminals 5 w.r.t. 1

 $U_o = 10.5V$ $I_o = 1.1 \text{mA}$ $P_o = 2.9 \text{mW}$

Hazardous Area Terminals 4 w.r.t. 3

 $U_o = 28V$ $C_i \ = \ 0$ $I_o = 93mA$ $P_o = 0.65W$

Hazardous Area Terminals 4 & 3 w.r.t. 1

 $U_o = 28V$ $I_o = 93\text{mA} \text{ at } 28\text{V}$ $I_o = 146\text{mA} \text{ at } 2.9\text{V}$

 $P_o = 0.65W$

Hazardous Area Terminals 5 & 4 w.r.t. 1

 $U_o = 28V$ $C_i = 0$ $I_o = 93\text{mA} \text{ at } 28\text{V}$ $I_o = 94mA$ at 27.5V

 $P_o = 0.65W$

Programming / Configuration Port (Jack Socket)

 $U_o = 8V$ $U_i \ = \ 9.1V$ $\begin{array}{ccc} C_i & = & 0 \\ L_i & = & 0 \end{array}$ $I_o = 15mA$ $P_o \ = \ 27mW$

Load Parameters

The capacitance and either the inductance or inductance to resistance ratio (L/R) of the load connected must not exceed the following values:

GROUP	CAPACITANCE	INDUCTANCE	OR L/R RATIO				
	(μF)	(mH)	(µH/ohm)				
Hazardous Area Terminals 2 w.r.t. 1, Hazardous Area Terminals 6 w.r.t. 1 or Hazardous Area Terminal							
6 w.r.t. 3							
IIC	2.41	181.4	967				
IIB*	16.8	725.6	1,333				
IIA	75.0	1,000	1,333				
I	95.0	1,000	1,333				
Hazardous Area Terminals 3 w.r.t. 1							
IIC	100	12.6	2,439				
IIB*	1,000	50.6	9,757				
IIA	1,000	101.2	19,515				
I	1,000	166.1	32,018				
Hazardous Area Terminals 5 w.r.t. 1							
IIC	2.41	1,000	12,313				
IIB*	16.8	1,000	49,254				
IIA	75.0	1,000	98,508				
I	95.0	1,000	161,616				

GROUP	CAPACITANCE (μF)	INDUCTANCE (mH)	OR	L/R RATIO (µH/ohm)		
				•		
Hazardous Area Termin	als 4 w.r.t. 3					
IIC	0.083	4.2		55		
IIB*	0.65	12.6		210		
IIA	2.15	33.6		444		
I	3.76	53.7		668		
Hazardous Area Termina	Hazardous Area Terminals 4 & 3 w.r.t. 1					
IIC	0.083	1.66		55		
IIB*	0.65	6.67		210		
IIA	2.15	13.3		444		
I	3.76	21.8		668		
Hazardous Area Termina	als 5 & 4 w.r.t. 1					
IIC	0.083	4.02		55		
IIB*	0.65	16.0		210		
IIA	2.15	32.1		444		
I	3.76	52.8		668		
Programming / Configuration Port (Jack Socket)						
IIC	0.367	60.7		360		
IIB*	2.15	243.0		1,441		
IIA	8.8	486.1		1,484		
I	12.32	797.5		1,484		

^{*} Group IIB parameters also applicable for associated apparatus [Ex ia Da] IIIC

Notes:

- 1) The above load parameters apply when one of the two conditions below is given:
 - the total L_i of the external circuit (excluding the cable) is < 1% of the L_o value or
 - the total C_i of the external circuit (excluding the cable) is < 1% of the C_o value.
- 2) The above parameters are reduced to 50% when both of the two conditions below are given:
 - the total L_i of the external circuit (excluding the cable) is $\geq 1\%$ of the L_o value and
 - the total C_i of the external circuit (excluding the cable) is $\geq 1\%$ of the C_o value.

The reduced capacitance of the external circuit (including cable) shall not be greater than $1\mu F$ for Groups IIB, IIA & I and 600nF for Group IIC.

16 Report Number

21(C)0386/13

17 Specific Conditions of Use

None



Issued 11 January 2022 Page 5 of 5

18 Essential Health and Safety Requirements

In addition to the Essential Health and Safety Requirements (EHSRs) covered by the standards listed at item 9, the following are considered relevant to this product, and conformity is demonstrated in the report:

Clause	Subject	Compliance
13	Protection against other hazards (LVD type requirements, etc.)	Manufacturer responsibility
14	Overloading of equipment (protection relays, etc.)	User/Installer responsibility
22(1)	External effects	User/Installer responsibility
22(2)	Aggressive substances, etc.	User/Installer responsibility

19 Drawings and Documents

Number	Sheet	Issue	Date	Description
CI5532-1	1 of 1	4	8.21	MTL5532 Certification Label Details and DIN rail
				fittings - Baseefa

These drawings are held with BAS21UKEX0461.

For other current drawings not re-submitted for this assessment, see Baseefa09ATEX158 - Issue 3